

MISHAP REPORT

159th AVIATION CO.  
CH47C 74-22288  
FT. CAMPBELL, KY.  
15 OCTOBER 1979

GROUND ACCIDENT - MAJOR

Aircraft was being ground run after installation of a combining transmission.

Pilot reported a thump followed by blade to blade contact. One rotor blade separated and struck another aircraft. The aft pylon separated from the aircraft. There was no fire reported.

The four crewmen exited the aircraft with no reports of any injuries.

Status of aircraft unknown at this time. Boeing personnel are enroute to provide technical assistance.

*see ?*



R. G. ORR

RGO:aty  
P41-37/X7937